

DART

DESIGN <i>AB</i>	DRAWN BY <i>AB</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>PH</i>	APPROVED <i>MM</i>	DRAWING NO. DSI 9369	REV. A SHEET 1 OF 1
DATE 07.02.13		TITLE STRUT REPLACEMENT	SCALE NTS
A	07.02.13	NEW ISSUE	


DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS D206-540 Rev. I

REF. CANADIAN STC: SH94-5

REF. FAA STC: SR00386NY

To eliminate interference with the forward hinge of the basket and the door, and to correct the length of the forward strut, it is acceptable to replace the D2749-1/3 Struts with D2749-9/11 Struts on some D206-540-013 Heli-Utility-Basket installations as shown below.



D206-540-013 INSTALLATIONS

**NOTE:
REPLACE EXISTING SADDLE WASHER WITH D2748 CLEVIS AND
RE-ATTACH USING EXISTING SADDLE HARDWARE.

CANADA DEPARTMENT OF TRANSPORT AIRCRAFT CERTIFICATION BRANCH DAO # 01-O-01	
APPROVED <i>Beepd</i>	
BY:	D. SHEPHERD (DE # 02)
DATE:	07.02.13
CERT. NO.:	SH94-5
ISSUE NO.:	4